
Veneer Manufacturing Principles




Veneer Manufacturing Principles


Crown cut



Quarter cut/semi quarter cut




Quarter cut







Pyramid cut




Peeled or rotary cut



Sling cut



Rift cut



Veneer Manufacturing Principles

1. - Log storage



2. - Quality control of logs



3. - Measuring of logs



4. - Shortening and subdivision



5. - Boiling of logs



6. - Prepping of logs



7. - Veneer manufacturing



8. - Veneer manufacturing



9. - Veneer cutting control



10. - Drying of veneer



11. - Veneer for cutting



12. - Measuring of veneer



13. - Quality control



14. - Veneer warehouse





